











vers.02.25

Chairman 500 (LUX)

RU ИНСТРУКЦИЯ ПО СБОРКЕ
EN ASSEMBLY INSTRUCTIONS
DE AUFBAUANLEITUNG
FR INSTRUCTIONS DE MONTAGE
IT MANUALE D'USO
ES INSTRUCCIONES DE MONTAJE
CZ NÁVOD K MONTÁŽI
KZ ЖИНАУ ЖӨНІНДЕГІ НҰСҚАУЛЫҚ








- 12 (M6x16) 8 pcs
- 13 (M6x20) 4 pcs
- 14 (M6x25) 2 pcs
- 15 (M8x20) 3 pcs
- 16 (Ø20x8x1,5) 3 pcs
- 17 (Ø20x8x4) 2 pcs
- 18 (3,5x20) 1 pcs



STEP 1
↓
STEP 2

Chairman 500 (LUX)



CHAIRMAN
ПОМОГАЕТ РАБОТАТЬ

chairman.ru
info@chairman.ru
vk.com/chairman_chairs