Assembling Instruction

_	T	O	
(1)Base	(2) Mechanism	A	C
X5		9 - (5) - 1 $- (5) - 2$	
(3)GasColumn	(4) Chair body		
(5)Screws			
		В	D
1. ① 2. ② 3. ①	X4 6X30MM X4 6X20MM X1 5MM		