




Chairman 535 (LT)

RU ИНСТРУКЦИЯ ПО СБОРКЕ
EN ASSEMBLY INSTRUCTIONS
DE AUFBAUANLEITUNG
FR INSTRUCTIONS DE MONTAGE
IT MANUALE D'USO
ES INSTRUCCIONES DE MONTAJE
CZ NÁVOD K MONTÁŽI
KZ ЖИНАУ ЖӨНІНДЕГІ НҰСҚАУЛЫҚ









10 (M6x10) 4 pcs

11 (M6x16) 4 pcs

12 (M8x20) 3 pcs






13 (M6x35) 6 pcs

14 9 pcs



STEP 1
 ↓
STEP 2

Chairman 535 (LT)



CHAIRMAN
ПОМОГАЕТ РАБОТАТЬ

chairman.ru

info@chairman.ru

vk.com/chairman_chairs